


Heavy Duty Punch Driver Knockout Set

for punching holes in 16 ga. to 10 ga. stainless steel



Model 162SS – ½" to 2" Heavy Duty Knockout Set





Operating, Maintenance, Safety and Parts Manual

08/11



Read and understand this material before operating or servicing any component of the Punch Driver Set. Failure to understand how to safely operate and service this unit may result in serious injury or death.

This manual is free of charge. All personnel who operate or service the Punch Driver Set should have a copy of this manual and read and understand its contents. To request a copy, call or write to the address below.

TABLE OF CONTENTS

fety Alerts
fety Information
ecifications
erating Instructions 4-6
t-Ups Diagram
mponents List
nintenance
ploded View
rts List

SAFETY ALERTS



Safety Alert Symbol

THIS SAFETY SYMBOL is used to call your attention to instructions that concern your personal safety. It means: ATTENTION! BE AWARE! THIS IS AN IMPORTANT SAFETY INSTRUCTION!

Read, understand and follow these safety instructions. Failure to follow these safety instructions may result in injury or death.

A DANGER

Immediate hazards which, if not avoided, WILL result in serious personal injury or death.

WARNING

Hazards or unsafe practices which, if not avoided, COULD result in serious personal injury or death.

A CAUTION

Hazards or unsafe practices which, if not avoided, COULD result in minor personal injury or property damage.

RETAIN SAFETY INFORMATION



This manual should be read and understood by all personnel who operate or service this Punch Driver. Failure to understand how to safely operate and service this unit could result in injury or death. This unit should only be operated or serviced by qualified personnel.

(**) IMPORTANT SAFETY INFORMATION

Follow ALL safety information provided by the manufacturer.

A DANGER NEVER use the punch driver or any of its components near live circuits.

WARNINGDO NOT continue to operate punch driver after the punch is complete.
Doing so could damage the punch driver and cause component failure resulting in serious injury or death.

▲ WARNING

If the punch driver motion stops before the punching process is completed, DO NOT continue to operate the punch driver. Reverse the drill, disassemble the set-up and determine the cause before continuing.

ALWAYS support the punch driver as the punch is completed. An unsupported punch driver could fall, causing injury.

ALWAYS thread the punch COMPLETELY onto the draw stud to avoid thread failure. If the punch tightens before it is completely threaded onto the draw stud, disassemble the set-up and determine the cause. Then reassemble the set-up.

A WARNINGNEVER attempt to exceed the punching capacity of this knockout set.

Doing so may cause component failure and possibly serious injury or death.

A WARNINGNEVER attempt to punch a hole through more than a single layer of material. Doing so may cause component failure and possibly serious injury or death.

A WARNINGNEVER use this punch driver set or any of its components except for its intended purpose.

A ½" cordless drill is sufficient to activate the punch driver. NEVER attempt to apply additional force to the punch driver. Doing so may cause component failure and possibly serious injury or death.

ALWAYS inspect every component of the punch set-up, including the punch driver, punch, die and draw stud, before each use.

Replace any worn or defective parts with Current Tools replacement parts. NEVER use dull punches.

A CAUTION NEVER use any component that has worn or damaged threads.

ALWAYS check to ensure all components are properly assembled before punching.

ALWAYS be aware of pinch points while operating the punch driver. Keep hands away from punch and die during punching operation.

ALWAYS keep hair and loose clothing away from rotating or moving parts.

A CAUTION New punches are sharp. Be careful when handling them.

ALWAYS wear safety glasses when punching.


(a) SPECIFICATIONS

Model No. **162SS** 19 lbs. Weight

½" to 2" conduit size holes in a maximum of 10 ga. (.134 thick) Capacity stainless steel

- Recommended Drill (Provided by end user) ½" cordless drill with a minimum of 18 volts.
- Current Tools[™] Model 162SS Piece Maker[™] SS is designed to split the slug into two pieces for easy removal from the die after punch completion. However, due to variations in the material to be punched, some slugs may not split into two pieces. These slugs will be distorted and easily removed from the die.
- Current Tools Punch Driver may be used with Greenlee®* Slug-Splitter®** and Slug Splitter SC^{TM**} punches, dies and draw studs.
- * Greenlee is a registered trademark of Greenlee/Textron.
- ** Slug Splitter and Slug Splitter SC are registered trademarks of Greenlee/Textron

OPERATING INSTRUCTIONS



- 1. Match the punch, die, draw stud and spacer as required for the size hole to be punched. (See figures 1a and 1b on page 7).
- 2. After marking the hole location, drill a hole as indicated below.

Conduit size Required hole size 1/2" 1/2" 7/2" 3/4" thru 2"

NOTE: Alternate Method for 3/4" thru 2" conduit sizes — Use the 1/2" punch and die to increase the hole size to accept the $\frac{3}{4}$ " draw stud (Part #1575).

3. Chuck the $\frac{3}{8}$ " nut driver (Part #163-14) into the cordless drill and slide onto the hex input shaft. Operate the punch driver until the draw shaft is flush with the end cap.

continued on next page . . .

4. When using the ½" punch and die: Thread the ¾"-½" X 4½" adapter draw stud (#1574) into the Punch Driver. Tighten the adapter draw stud using the screwdriver slot located at the end of the adapter draw stud.

When using $\frac{3}{4}$ " through 2" punch and dies: Thread the $\frac{3}{4}$ " X 5 $\frac{1}{2}$ "draw stud (Part #1575) into the Punch Driver. Tighten the draw stud using the screwdriver slot located at the end of the draw stud.

Determine if spacer is needed and install. (See Spacer Chart below).

SPACER	SPACER CHART			
Punch & Die Size	Spacer			
1/2"	No spacer			
³¼" thru 1¼"	S			
1½" – 2"	No spacer			

- 5. Slide the die onto the draw stud with the open end of the die facing away from the punch driver.
- 6. Place the draw stud through the hole you drilled in step 2. Then thread the punch onto the draw stud with the cutting face toward the material to be punched. Thread the punch onto the draw stud until the punch and die are snug against the material.

AWARNING

ALWAYS thread the punch COMPLETELY onto the draw stud to avoid thread failure. If the punch tightens before it is completely threaded onto the draw stud, disassemble the set-up and determine the cause. Then reassemble the set-up.

- 7. Complete the punching process by attaching the $\frac{1}{2}$ " cordless drill with nut driver (minimum 18 volts recommended) to the hex input shaft of the punch driver.
 - Operate the drill in FORWARD to complete the punch.
 - After the punch is completed, run the drill in REVERSE until the draw shaft is at least flush with the end cap.
 - After unloading slug, return the draw shaft until it is flush with the end cap.

NOTE: Whether to operate your drill in low or high gear will be determined by hole size, thickness and type of material to be punched, battery strength and voltage of your drill.

AWARNING

- DO NOT continue to operate punch driver after the punch is complete. Doing so could damage the punch driver and cause component failure resulting in serious injury or death.
- If the punch driver motion stops before the punching process is completed, DO NOT continue to operate the punch driver. Reverse the drill, disassemble the set-up and determine the cause before continuing.
- ALWAYS support the punch driver as the punch is completed. An unsupported punch driver could fall, causing injury.


ACAUTION

ALWAYS be aware of pinch points while operating the punch driver. Keep hands away from punch and die during punching operation.

SET UPS


EXPLODED VIEW

COMPLETED VIEW



COMPONENTS

PUNCH DRIVER




COMPONENTS LIST

ITEM#	CATALOG#	DESCRIPTION	<u>163</u>	<u>162SS</u>
1	163	Punch Driver	1	½" to 2 " 1
		Nut Driver		
3	1574 ³ ⁄4"-	$^{7}/_{16}$ " X $4^{1}/_{4}$ " SS Adapter Draw S	tud	1
4	1575	¾" X 5½" SS Draw Stud		1
5	1553	Spacer – S		1
6	1505	Metal Case – 162SS		1
7	1536	¹ ⁄₂" SS Punch		1
8	1537			1
9	1538	³ ¼" SS Punch		1
10	1539			1
11	1542	1" SS Punch		1
12	1543	1" SS Die		1
13	1544	1¼" SS Punch		1
14	1545	1¼" SS Die		1
15	1546	1½" SS Punch		1
16	1547	1½" SS Die		1
17	1548	2" SS Punch		1
18	1549	2" SS Die		1

MAINTENANCE

- 1) The Model 163 Punch Driver gearbox is lubricated from the factory and should not require additional lubrication.
- 2) Yearly Using a good quality MP grease, grease the acme threads on the draw shaft (see exploded view on page 9. Item #3).
- 3) Keep all components clean and free of any debris.

MODEL 163 PUNCH DRIVER



ITEM #	PART #	<u>QTY</u>	DESCRIPTION
1	163-1	1	Gearbox
2	163-591	1	Housing-Draw Shaft
3	163-593	1	Draw Shaft
4	163-665	1	End Cap
5	163-12	4	Screw-Skt. Hd. Cap - 10-32 × %"
			Key
			Screw-Button Hd. Skt. – ½-20 × %"
			Screw-Button Hd. Skt. – 10-32 × 5/16"
			Key ¼" x ¾"
			Plate-Cover, Bottom
			Plate-Cover, Input
			Screw, Button Hd. Skt. – ½-20 × 5/16"
			Bushing – Bronze
			Washer – 14 Gauge
			Washer – ³ / ₁₆ " Polyurethene